CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

	SECRET SECURITY INFORMATION		25X1A
DUNTRY	Hungary	REPORT NO.	
BJECT	Sheet Metal Factory at Borsodnådasd	DATE DISTR.	12 August 1953
	25X1A	NO. OF PAGES	3 25X1A
TE OF INFO.		REQUIREMENT	
ACE ACQUIRE		REFERENCES	
ACE ACGOINE			
	THE SOURCE EVALUATIONS IN THIS REPORT THE APPRAISAL OF CONTENT IS T (FOR KEY SEE REVERSE)		
out	s Sheet Metal Factory was located in a deside of the town of Borsodnadasd /4808N-ath of Ozd /4813N-2018E/. Because of the	2015E/, which is abo hilly terrain surro	ut 10 km. unding the
out sou	s Sheet Metal Factory was located in a deside of the town of Borsodnadasd /4808N-ath of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility of the supied an area of 100 x 400 m., and within	2015E/, which is abo hilly terrain surro f expanding it. The	ut 10 km. unding the factory
out sou	seide of the town of Borsodnadasd 74508N- th of Ozd 74813N-2018E7. Because of the story, there was hardly any possibility of supied an area of 100 x 400 m., and within Main Workshop	2015E/, which is abo hilly terrain surro f expanding it. The	ut 10 km. unding the factory
out sou	which of the town of Borsodnadasd /4508N- th of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility o supied an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products	2015E/, which is abo hilly terrain surro f expanding it. The n the compound were	ut 10 km. unding the factory
out sou fac occ	seide of the town of Borsodnidasd /4508N- th of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility o supied an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material	2015E/, which is abo hilly terrain surro f expanding it. The n the compound were	ut 10 km. unding the factory
out sov fac occ a. b.	which of the town of Borsodnadasd /4508N- th of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility o supied an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products	2015E/, which is abo hilly terrain surro f expanding it. The n the compound were	ut 10 km. unding the factory
put sov fac occ 'a. b. c. d.	side of the town of Borsodnidasd /4508N- th of Ozd /4813N-2018E/. Because of the trory, there was hardly any possibility o tupied an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material Administration Building House of Culture and Factory Garages	2015E/, which is abo hilly terrain surro f expanding it. The n the compound were	ut 10 km. unding the factory
put sou fac occ occ occ occ occ occ occ occ occ o	seide of the town of Borsodnådasd /4508N- with of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility of supied an area of 100 x 400 m., and within Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material Administration Building House of Culture and Factory Garages Factory Yard	2015E/, which is abo hilly terrain surro f expanding it. The n the compound were	unding the factory the following:
put sou fac occ a. b. c. d. f.	side of the town of Borsodnidasd /4508N- th of Ozd /4813N-2018E/. Because of the trory, there was hardly any possibility o tupied an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material Administration Building House of Culture and Factory Garages	2015E/, which is about the hilly terrain surround fexpanding it. The note compound were as a second to the compound were second to the compound workshop there were second to the compound the com	unding the factory the following: asisted of two ad three or four tempering furnaces
put sour factors occurs	side of the town of Borsodnadasd / 1508N- th of Ozd / 1813N-2018E/. Because of the story, there was hardly any possibility o supled an area of 100 x 400 m., and withi Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material Administration Building House of Culture and Factory Garages Factory Yard Main Workshop was a one-story building, sts. In the front part were 12 hot-milli- wring furnaces. In the rear part of the	2015E/, which is about hilly terrain surrof expanding it. The note compound were not be compound were as a 200 m. It compounds the compound were not one ton capacity ocated north of the latest the building was us	unding the factory the following: sisted of two distributions furnaces tempering furnaces fain mually
put sour factors occurs	side of the town of Borsodnidasd /4508N- with of Ozd /4813N-2018E/. Because of the story, there was hardly any possibility of supied an area of 100 x 400 m., and within Main Workshop Warehouse for Finished Products Storage Building for Auxiliary Material Administration Building House of Culture and Factory Garages Factory Yard Main Workshop was a one-story building, with the front part were 12 hot-milling wing furnaces. In the rear part of the sere were also two electric furnaces, each warehouse for Finished Products was lookshop. It occupied an area 10 x 60 m.	2015E/, which is about hilly terrain surrof expanding it. The note compound were not the compound were so workshop there were not one ton capacity ocated north of the Market This building was usually be about the terrain of the terrain of the market products. The terrain surrounding was usually surrounded to the market terrain of the Market This building was usually surrounded to the terrain of the terrain of the market terrain of the Market This building was usually surrounded to the terrain of the market terrain of the Market This building was usually surrounded to the terrain of the market terrain of the Market This building was usually surrounded to the market terrain of the Market This building was usually surrounded to the market This building was usually	unding the factory the following: sisted of two distributions furnaces tempering furnaces fain mually

Approved For Release 2002/07/22 : CIA-RDP80-00810A001600820003-1

Approved For Release 2002/07/22: CIA-RDP80-00810/	A001600820003-125 Χ 1 Δ
---	-------------------------

SECRET	/SECURITY	INFORMATION	
	•		

from enterprises using the plates manufactured in the factory trans-
ported them right from the loading ramp, and often waited in the yard
for plates to be finished. Thus there was no necessity for storing
the finished products. This Warehouse was headed by (fnu) CSOMA, $25X1$
under the direction of the Materials and Goods Distribution Division
of the Foundries and Machine Industries Ministry

1.2

- 4. On the left-hand side of the Main Workshop, facing the entrance, was a new two-story building 40 x 20 m. for storing auxiliary materials. Factory offices were located on the second floor of this building.
- 5. On the right-hand side, near the entrance to the factory, was a building, 15 x 30 m., in which were located the factory administration offices, the secretary's office, and the office of the technical management of the factory.
- 6. On the square facing the factory were the House of Culture and the factory garages.
- 7. Along the road leading from the factory to the town there were long rows of living quarters for factory officials and workers. These buildings had been constructed before World War II.
- 8. In the yard of the factory large quantities of basic materials were kept in the open. Part of the yard was reserved for cranes.
- 9. The factory had 12 hot-milling twin cylinders, three or four glowing furnaces, and two electric furnaces of one ton capacity each. The cylinders could not be produced in Hungary because of the lack of reverberatory furnaces. Until 1950 the cylinders were imported from West Germany. The last shipment of 12 cylinders from West Germany in 1950 was held up by US authorities in Linz and later returned to West German enterprises. As a result of this, sheet metal production fell off in the Borsodnadasd Sheet Metal Factory. In order to remedy the situation the Hungarian Government ordered cylinders from Poland. Of the five cylinders delivered by Poland in 1951, two cracked after a few hours of use and the remaining three cracked within two months. The damage amounted to more than one million forints. In contrast to this, West German cylinders had lasted more than one year.
- 10. Because of the poor quality of Polish cylinders, in 1951 an agreement was made with the Soviet Union for the purchase of cylinders for 1952. The import of cylinders was managed by the state trading agency METALIMPEX (Magyar Acelipari Kuelkereskedelmi Vallalat Hungarian Foreign Trade Enterprise for Steel Industry). But the Soviet cylinders were no better than the Polish.
- II. The Ozd Metallurgical Works supplied the Borsodnadasd Sheet Metal Factory with ingots and blocks of steel necessary for the production of sheet metal. It also supplied the factory with iron needed by the electric furnaces. However the work of these furnaces was frequently interrupted for several hours or even several days because of delay in delivery of iron. The Ozd Works also supplied the factory, as well as the municipality of Borsodnadasd, with electric power. The factory was connected with the Ozd Works by a narrow-gauge railroad track. The necessary coal was obtained at the site of the factory, where it was transported on conveyor belts from the mine.
 - 12. This was the only fine sheet milling factory in Hungary. The sheet metal produced was 0.1 3 mm. thick, the maximum size 2 x 3 meters. It was black, polished, tinned, or galvanized. All of Hungarian industry was dependent on this factory for fine metal sheet, which had manifold uses, from radio condensers to automobile bodies.

SECRET

SECRET/SECURITY INFORMATION -3-

- 13. After being rolled to the desired thickness, the metal sheet was cut on the cutting machines to required size, piled up, and transported to the tinning and galvanizing sections. The hot milling consisted in milling ingots and steel blocks at 800 degrees C. During this process the cylinders had a temperature of 300 degrees C. Sheet metal scrap left over after cutting was pressed by machines into bundles of 100 kg. and sold back to the Ozd Metallurgical Works for re-use.
- 14. The factory employed 1,300 1,500 workers (women worked only in offices), and operated in three shifts. The workshop was badly ventilated. It was full of smoke and gases from the hot metal, and the temperature was 50 60 degrees C. The work tempo was exhausting because the workers were constantly driven to produce more in order to fulfill the high norms. This speed actually caused frequent stoppage of work because of cracking cylinders. The workers had to make up for the time lost through breakdowns.
- 15. In March 1952 (fnu) TOTH was director of the factory. He was about 40 years old, of medium build, slender, bald, with blue eyes and a narrow face. He was a laborer in the Ozd Metallurgical Works before he was appointed director of the Borsodnadasd Sheet Metal Factory in the Summer of 1951. For several months previous to his appointment there had been no director, and the factory was managed during that period by a senior technical specialist.

SECRET